### Er. J. VARA PRASAD

BE, DCM, C. ENG. (i), FIV

AMIE, M.I.STRUCT.E

CHARTERED ENGINEER,

APPROVED ENGINEER BY PWD & IN COLLECTOR'S PANEL

TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

283/35, 2<sup>nd</sup> Floor, Jai Hind Flats

Belly Area, Anna Nagar (West),

Chennai - 600 040

Email:jvprasaad@gmail.com

Office: 99623 54541

Cell: 9623 99199,

# STATEMENT ACCOMPANYING FORM 'A 'STRUCTURAL STABILITY

-Name of the School **ABS GLOBAL SMART SCHOOL** 

Location street No. Ward No .. .. No.16, J.N.Road,

2.

V.M.Nagar, (Opp To Municipal office

Thiruvallur Town,

Name of place, (i.e.) corporation Thiruvallur Taluk & District,

Pin - 602 001.

S Year of Construction

Municipality / Panchayath /

RCC: GF - 2023 -New

RCC: TH 2023 - New

4 Approximate Cost of Construction . . About Rs.50.00 Lacs per Floor

Purpose for which the building is . . For Conducting School Classes

being used or proposed to be used

5 hitherto been used Purpose for which the building has . . For Conducting School Classes

6 Details of construction of the building

(particulars) of the foundation, soil

specification of the various parts as under

Foundation RCC Isolated Footings, Grade Beam

RCC Columns, Brick Work in Cement Mortar, Plinth Beam

0

Basement

0 Superstructure RCC Columns, Beams, Brick Work in Cm,

RCC Framed Structure

d. Floor & Roof ,are to be given -RCC,

Flooring: Vitrified Tiles, Granite

Period for which license is required .. From 01.04.2023 to 31.03.2026

FOR THREE YEARS ONLY

About 1400 Pupils.

00

No. of Persons to be accommodated:

Date

: 01.02.2024

Signature of the Authorized person

Place

Chennai

7.

( Rupees One Thousand four Hundred Pupils Antw

PGDCM.,C.Eng.FIV.,MIE.,MICA., Chartered Engineer Approved Engineer in Collector's Panel M.I.Struct E.

Competent Person to Issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats, Anna Nagar West Belly Area, NR, Chinmaya School - 600 040.

Cell: 99623 59159, 94433 79627 Off: 78583 94549, Ph.: 1044 - 2626 0799

### STATEMENT TO ACCOMPANY THE REPORT OF STRUCTURAL SOUNDNESS FORM -0

FOR THREE YEARS ONLY (One Thousand four hundred Pupils Only) (Subject to Remarks)	Thousand four hundr	YEARS ONLY (One	FOR THREE	School Classes
The Building is Structurally Sound	About <b>1400</b> Pupils	01.04.2023 to 31.03.2026 About 1400 Pupils	01.04.2	For Conducting
	persons accommodated.	for which the license is required	for which t is required	The building is To be used
Remarks	No. of		Period	Purpose for which
Roof : RCC , Flooring: Tiles, Granite		RCC : FF - 2023 - New	RC	Pincode- 602 001,
RCC Framed Structure		RCC : GF- 2023 - New	RC	Thiruvallur,
RCC Columns, Beams, Brick work in cm		l office)	to Municipa	V.M.Nagar, (Opp to Municipal office)
Brick Work in Cm, Plinth beam				No.16, J.N.Road,
RCC Isolated Footings, Grade Beam	loor RCC : GF,FF	ABS GLOBAL SMART SCHOOL About Rs.50 Lacs/ Floor RCC: GF,FF	RT SCHOOL	ABS GLOBAL SMA
Masonry.			ce.	& Name of the Place.
framed or load bearing	Building Buildings	Bui		No. Street Name
of structure, steel RCC	Storeys	the Building the		<b>Building door</b>
Short Description	of No of	Value of Age of		Location of the
	the saw was the saw and the saw was the saw saw and the	the set on the first out and the set of our set of our set one and the set on our out of our out of our out of	and stade stade stade stade stade stade state	and they are any part and any and any they are

part this report Aspects such as Title not held responsible and this Report gets Invalid and automatically gets cancelled. Further this Report covers the violations/ Lapse in safety norms are found at a later period after issue of this Report / License The Engineer is on the date of inspection. Construction waste, debris and any other waste material should not be stored in any Grills . This Certificate is issued based on physical inspection of the structure and actual available in the premises working hours. All Necessary safety standards has to be Strictly adhered / Followed. Emergency periodically maintained. Any precaution. Weathering coarse for terrace and Water Proofing / Treatment has to be done to the Roof and to be Run on the open ground/ flooring it has to be put in Cable Trenches covered by slabs with at most safety and Main Switches/Cables, electrical points, wiring / Gadgets has to be checked properly and to be maintained periodically. All Panel Boards, Periodical Repairs and Renovations Shall be carried out to the Entire Building Block regularly. Further Necessary made subsequently structural soundness has to be obtained. Emergency Exit to be provided as per norms. fire fighting equipment's should be kept in the premises and should be trained for operation. If any fire accident Mishap occurs we are not held responsible. Structural Alteration / Deviation Should Not be Carried out to of the hold Property. AC Sheet / Metal sheet roof shed is not Considered in this Certificate. If any deviation/ Any This Report does not include any Eventualities caused by Natural Calamities. We here by advise that the said Mentioned Building only. Pls whole Building without Prior Permission from the Competent Authority. If any additional construction is has to be Provided as per norms. Open Terrace, Additional construction is done subsequently structural soundness has to be obtained. This is a building and in the whole premises. This Certificate Covers RCC: GF, , Ownership has to be kept in Lock and Key position. Electrical Conduits/ Cables should not be loosely Construction/ Repairs/ Alteration work should not be carried out during School Encumbrances if any were Confirm the Survey No with Patta, Approved Corridor and Staircase must be barred not considered and as it is not within this scope of **FF Roof Permanent Structure** Plan and Title Deed. with Exit Doors, safety A

Date 01.02.2024 Signature of the Authorized person

> PGDCM., C.Eng. FIV., MIE., MICA., M.I. Struct E Chartered Engineer

Approved Engineer in Collector's Panel

Competent Person to Issue Stability Certino. 283/35, 2nd Floor, Jai Hind Flats. Belly Area, NR, Chinmaya School

Anna Nagar West, Chr Cell : 99623 99199, Off : 78083 94949, Ph.:

2625 0799

#### FORM - C

Form of Report of structural soundness under sub-section (4) of section 4 of

Tamil Nadu public (Licensing) Rules, The Tamil Nadu public building (licensing) Act 1965 (Tamil Nadu act 1 of 1965) Referred to in rule 4 of the 1966

We have inspected the building mentioned in the statement and furnish below its salient technical

#### features:

-Foundation:

a Depth below ground level About 1.82 Mts

5. Nature of Soil met with at

foundation level. Clayee Soil

0 Pressure at foundation

0 Probable Safe bearing capacity of

The Soil Strata met with at foundation About 15 Mts. / Sq. M

12 Superstructure Brick work in Cm

a Minimum stress in the most

Critical section of within Limits

Masonry and concrete

0 Nature of masonry and concrete **Brick Masonry** 

And its safe permissible stress . . within Limits

( latest Version )and other relevant Indian standards Code of Practice and I declare that the building is

Structural soundness of the Building has been Verified by me with reference to I.S.I Loading Standards 875

Structurally Sound (Subject to Remarks) to be used as Public Building noted in the Statement.

from 01.04.2023 to We are of the Opinion that the building is structurally sound. A license can be granted for the period 31.03.2026 (FOR THREE YEARS ONLY)

Place: Chennai.

Date 01.02.2024 Signature of the Authorized person

#### ARA PRASAD,

PGDCM.,C.Eng.FIV.,MIE.,MICA.,M.I.Struct E.,
Chartered Engineer,

Approved Engineer in Collector's Panel, mpetent Person to Issue Stability Certific No. 283/35, 2nd Floor, Jai Hind Flats, Certificate

Belly Area, NR, Chinmaya School, Anna Nagar West, Chennai - 600 040. Cell: 99623 99199, 94433 79627 Off: 78583 94949, Ph.: 044 - 2626 0799

#### J. VARA PRASAD

APPROVED ENGINEER MICA, MIE, M.I.STRUCT.E BE, PGDCM, C. ENG. (i), FIV ENGINEER,

TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

283/35, 2<sup>nd</sup> Floor, Jai Hind Flats

Belly Area, Anna Nagar (West),

Email: jvprasaad@gmail.com

CELL: 99623 99199, 94433

Office: 99623 54541

ANNEXURE TO "STATEMENT ACCOMPANYING FORM - A"

**Entire Building** other floors etc., We here by advise That the Periodical Repairs and Renovations Shall be carried out to the Buildings/ Blocks or Structures Such as Compound wall ,Semi/ Non-permanent Structures either in GF or in any No.16, J.N. Road, V.M.Nagar, (Opp to Municipal office) Thiruvallur, Pincode-602 001. The Following Building RCC: We have inspected the School Building Premises of ABS GLOBAL SMART SCHOOL, Located GF -Block regularly. 2023 -New, RCC: FF - 2023 - New S available. This Report does not include any other S

cancelled. Further this Report covers the above said RCC Roof Building alone only. AC Sheet / Metal sheet shed this Report / License construction debris. All Necessary safety Norms and standards has to be Strictly adhered/ Followed. This is Cleaning necessary guidelines has to be obtained and followed according to Pollution control Board Norms. The OHT, Inspection Chamber Openings has to be Sealed with cover slab and with regard to Waste Disposal and Subsequently obtained. Electrical Conduits/ Cables should not be loosely Run on the open ground/ flooring it Floors / Blocks the necessary approvals / Structure treatment is to be done as per standards. Weathering coarse for terrace and Water Proofing / Treatment has to points, wiring / Gadgets has to be checked properly and to be maintained regularly. Periodic water proofing physical inspection of the structure and actual available in the premises on the date of inspection. All Electrical norms. Structural Alteration / Deviation Should Not be carried out to any of the block for Whole Building Or any operation. If any fire accident / Mishap occurs we are not held responsible. Emergency exit to be provided as per Encumbrances if any were done to the Roof and to be periodically maintained . Any Construction/ Repairs/ Alteration work should not carried out during School working hours. This Report does not cover any Structure / Partly completed other Non permanent premises be put in Cable Trenches covered by slabs with at most safety and precaution. Building Further Necessary firefighting equipment's should be or building under property. should be kept in neat and clean position without any Without Prior Permission from the The Engineer is not held responsible and this Report gets Invalid and automatically If any deviation/violations/Lapse in safety norms are found at a later period after issue of structure is not Considered in this not considered and it is not within this scope of Certificate construction. Any Further additional construction either in G.F, FF structural design / structural Soundness Competent Authority. Certificate. kept in the Legal Aspects such as premises and should be This Certificate is dumping of The UG sump, manholes, certificate has waste material and issued Title, or in any other trained Ownership based to be for

. . Chennai

Date 01.02.2024 Signature of the Authorized person

## ARA PRASAD


PGDCM., C.Eng. FIV., MIE., MICA., M.I. Struct E

Competent Person to Issue No. 283/35, 2nd Floor, Chartered Engineer, Approved Engineer in Collector's Panel Stability

Anna Nagar West, Belly Area, NR, Chinmaya School t, Chennal - 600 040. 199, 94433 79627

#### **PHOTOCOPIES**







Signature of the Authorized Person

J.VARA PRASAD,
PGDCM.,C.Eng.FIV.,MIE.,MICA.,M.I.Struct E.,
Chartered Engineer,
Approved Engineer in Collector's Panel,
Competent Person to Issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats,
Beily Area, NR, Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Cell: 99623 99199, 94433 79627
Off: 78583 94949, Ph: 044 - 2626 0799









PGDCM.,C.Eng.FIV.,MIE.,MICA.,M.I.Struct E.,
Chartered Engineer,
Approved Engineer in Collector's Panel,
Competent Person to Issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats,
Belly Area, NR, Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Cell: 99623 99199, 94433 79627
Off: 78583 94949, Ph: 044 - 2626 0799


















Signature of the Authorized Person

PGDCM.,C.Eng.FIV.,MIE.,MICA.,M.I.Struct E.,
Chartered Engineer,
Approved Engineer in Collector's Panel,
Approved Engineer in Collector's Panel,
No. 283/35, 2nd Floor, Jai Hind Flats,
Cell: 99623 99199, 94433 79627
Off: 78583 94849, Ph: 1844 - 2625 0799